

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE
(County)

Located In:

Corner Code #

1. Public Land Survey

T35N R. 29W I-7

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

RECEIVED FOR RECORD
97 JUL 23 PM 3:34
PAGE # 495 BK 5
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on June 26, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1852: Original Survey by Francis Coleman - B.T.'s - Hemlock, 8" - N10°W - 36 lks.; Y. Pine, 20" - S24°E - 130 lks. All original evidence for this corner has been destroyed by logging activities.

1970: Plat of Survey by George B. Wilson, RLS No. 17607, shows this corner as it relates to other corners in Section 14, T35N-R29W. He also shows his method of retracing the Government Meanders and ties to an Island to establish the line between Sections 14 and 23. He then establishes the corner on this line and at a distance of 2640' West of the Section Corner. The legend of his map indicates that he set a 4 inch dia. concrete monument, 30" long at this position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We retraced the line between Sections 14 and 23, T35N-R29W from the Corner of Sections 13, 14, 23 & 24 and found 4 inch square concrete monuments at a distance of 1320.31 feet (E1/16 Corner on line between Sections 14 & 23) and 2640.62 feet (1/4 Corner between Sections 14 & 23). We accepted the position of the existing concrete monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Accepted Existing 4" x 4" Concrete Monument:

7" dia. Maple	N86°E	40.85 feet	Scr. NBT
Twin Maples - 6" dia. & 12" dia.	S32°E	13.41 feet	Scr. NBT
12" dia. White Pine	N84°W	61.34 feet	Scr. NBT
8" dia. Basswood	N12°W	38.68 feet	Scr. NBT
Metal Survey Sign Post	North	0.9 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Jul. 09, 1997



REMONUMENTATION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1985

495

DEC 22 1997

COMMISSION