

SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 12/30, 1997
Mike Davis RLS
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MENOMINEE
(County)

Located In:

Corner Code #

1. Public Land Survey

T 35N R 29W

J/K - 9

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on Sept 17, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by FRANCIS COLEMAN - B.T.'s - Y. Pine, 7" - N40°E - 18 lks.; Y. Pine, 6" - S51°E - 22 lks. All original evidence for this corner has been destroyed by logging activities.
- 1985: George Wilson's survey states in legend that HDR MONUMENT, 4" Dia. Cap, 5' long stem - MEANDER COR. was set at this location.
- 1987: Certified Survey No. 552 recorded by William Lenca, RLS No. 26461, shows Fd HDR Mon. for the Meander Corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 3/4 inch diameter aluminum rod with a 3-1/4 inch diameter aluminum cap (known as a Berntsen HDR Monument) set on the bank of the Menominee River as indicated in George Wilson's 1985 survey. This monument has been used in several surveys and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 3/4" dia. Alum. Rod 5' long w/3-1/4" Alum. cap (HDR Monument) for corner location:

18" dia. White Oak	N27°E	47.85 feet	Scr. NBT
8" dia. Jack Pine	S63°E	28.19 feet	Scr. NBT
9" dia. Jack Pine	S13°E	44.50 feet	Scr. NBT
Menominee River Bank	West	6.0 feet	
Metal Survey Sign Post	East	1.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Sept 30, 1997

