

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 36 N.R. 1s 24 & 25 W

36N, R24W
S

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to north and to south. Stumps burnt and rotted in area. No original evidence found.

SURVEYOR'S SEAL

SIGNED THE TIME TO SURVEYOR FRANK J. Bray