

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

for corners in

Menominee (County)	Located In:	Corner Code #
Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
Property Controlling n Section	S 5 T 36N R 24W S 5 T 36N R 24W S _____ T _____ R _____	02 06 _____
Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
Lot No. _____, Recorded Plat _____		
Private Claims		

Jeremy J. Pipp, in a field survey on 2/11/2014 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
in this certificate.

Description of original monument and accessories and/or subsequent restoration:

02) East One-Sixteenth corner common to Sections 32 and 5. Not set in original survey. 1967:  
Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap witnessed by 7" W. Birch S82E  
9 links (12.54'), 8" W. Birch S77W 24 1/2 Links (16.17').

06) Northeast One-Sixteenth corner of Section 5. Not set in original survey, no evidence of  
subsequent establishment.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

02) No Evidence of MDNR monument or witnesses; location falls in existing camp yard and likely  
destroyed. Found 2" Galvanized Pipe +/- 8 feet tall 0.7 feet East of calculated position. Corner  
position remonumented mid-point and on-line between the North One-Quarter corner and the Northeast  
corner of Section 5. Above noted 2" pipe left as noted East of monumented position.

06) Corner position established at the intersection of the North and East One-Sixteenth lines of  
Section 5. Position falls in West rut of two track Access Road and +/-13 feet NE of existing Gate.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

02) DNR monument  
4" Maple N48E 6.46' (1/16S,BT)  
4" Maple S70E 49.86' (1/16S,BT)  
4" Maple S12W 44.80' (1/16S,BT)  
NE Cor of Camp N85W 40.77'

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

Signed by \_\_\_\_\_  
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources,

(06) DNR monument  
4" Cherry N22E 38.62' (1/16S,BT)  
5" Maple S28E 13.25' (1/16S,BT)  
6" Ash S89W 20.07' (1/16S,BT)  
6" Ash N39W 15.70' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

Date July 9, 2014



20305

20306

Revised May 14, 1975  
Revised Jan., 1983  
Revised Oct., 1995