

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Menominee	Located In:	Corner Code #
(County)		
Public Land Survey	T 36N R 24W	C02
	T R	
	T R	
Property Controlling Section	S T 36N R 24W	05
	S 5 T R	
	S T R	
Miscellaneous Property in Sec.	S T R	
	S T R	
Lot No. , Recorded Plat		
Private Claims		

2/12/2014
Jeremy J. Pipp, in a field survey on 2/11/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
in this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

C02) Quarter corner common to Sections 5 and 6. 1848: James Mullett, DS. Set quarter section
corner post witnessed by Fir 6 N73E 16 links (10.56'), Birch 6 S65W 21 links (13.86'). 1967:
Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap at "single proportioned
distance between section corners to north and to south and on line between same", witnessed by 8"
Maple S70W 48 1/2 links (32.01'), 15" Cedar N15E 51 links (33.66').

05) Center-North One-Sixteenth corner of Section 5. Not set in original survey, no evidence of
subsequent establishment.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C02) Accepted found MDNR Monument and NBT Witnesses (Maple = living, Cedar = dead & down).
Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original
corner.

05) Corner position established by proportionate measurement and on-line between the Center One-
quarter corner and the North One-Quarter corner of Section 5.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C02) DNR monument
5" Ash N68E 34.71' (1/4S,NBT)
5" Maple S29E 19.17' (1/4S,NBT)
EX 23" Maple S73W 32.86' (1/4S,NBT)
4" Ash N24W 14.31' (1/4S,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
metal sign post was set North 1.5 feet.
Signed by

Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(05) DNR monument
5" Maple N25E 37.29' (1/16S,BT)
14" Cedar S23W 82.78' (1/16S,BT)
5" Ash S68W 46.35' (1/16S,BT)
4" Ash N42W 45.38' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Date July 9, 2014

