

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

✓ **LAND CORNER RECORD**

T. 36 N. R. 25


Menominee COUNTY

DESCRIPTION OF CORNER Section ~~corner~~ corner for sections ^{3/2} 10/11

CORNER MONUMENT 1" Iron pipe with 4" Aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/3/67, Frank J. Bray

WITNESSES TO CORNER..... 8" spruce (S11)(NBT) S 01° E, 15½ Links



16" Balsam (S3)(NBT) N 05° W, 107½ Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced from pine stump bottom to NW and rotted wood where Hemlock may have stood.
Corner checks fairly well with swamp edges to N, S, E and W.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/8/67
REGISTERED LAND SURVEYOR