LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| Menominee (County) | Located In: | Corner Code # | | | | | |
|---|--|---|--|--|--|--|--|
| 1. Public Land Survey | TR | | | | | | |
| 2. Property Controlling in Section | T R S 20 T 36N R 25W S 20 T 36N R 25W S T R | 10 08 | | | | | |
| 3. Miscellaneous Property in Sec. | S T R S T R | | Decision of Decision & File New Local | | | | |
| 4. Lot No, Rec 5. Private Claims | corded Plat | | Register of Deeds Stamp & File Number A B C D E F G H I J K L M | | | | |
| | 12/13/201: | 2AD | 2 5 4 4 3 2 1 1 | | | | |
| ı, Jeremy J. Pipp , in | a field survey on 12/13/2012 | 2AD do hereby state | 3 | | | | |
| that under requirements of P.A. 7 | الفاء المتالة المالة المالة | | | | | | |
| above were in conformance with regulations and rules therefore as required in the current manual of survey 5 | | | | | | | |
| instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13 | | | | | | | |
| a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 | | | | | | | |
| the rules of the Michigan Board | 8 19 20 21 22 23 24 | | | | | | |
| re-established, monumented, recove | 9 | | | | | | |
| NOTE: Not more than 2 corn on this certificate. | ers, all in the same town and range, | 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 | | | | | |

- A. Description of original monument and accessories and/or subsequent restoration:
- (10) South One-Sixteenth corner common to Sections 19 and 20. Not set in original survey, no evidence of subsequent establishment.
- (08) Center-West One-Sixteenth corner of Section 20. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (10) Corner position established mid-point and on-line between the West One-Quarter corner and the Southwest corner of Section 20.
- (08) Corner position established mid-point and on-line between the Center One-Quarter corner and the West One-Quarter corner of Section 20.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| (10) | DNR monument | | | (0) | (08) | | monum | ent | | |
|--------------------------------------|--------------|--------|------------|--|-----------|-----|--------|----------|------------|--|
| 10" R. Pine | N32E | 30.54' | (1/16S,BT) | 6" | Beech | | S76E | 27.85' | (1/16S,BT) | |
| 11" R. Pine | N68E | 33.55' | (1/16S,BT) | 6" | Ironwood | | S19W | 14.06 | (1/16S,BT) | |
| 11" R. Pine | \$57E | 45.57' | (1/16S,BT) | 9" | Maple | | N79W | 16.96 | (1/16S,BT) | |
| 9" R. Pine | \$22E | 32.96' | (1/16S,BT) | 4" | Beech | | N31W | 18.40' | (1/16S,BT) | |
| All trees are blazed, scribed, and | | | | Allerros are blazed, scribed, and | | | | | | |
| painted. Measurements are to nail in | | | Ra | paint LC4 Measurements are to nail in side of trae, rearings are magnetic. | | | | | | |
| side of tree, bearings are magnetic) | | | | 1 61 | de of tre | 4 2 | earing | s are ma | agnetic. | |
| | / | | /// | 1 2 | | / 3 | br | | _ | |

Surveyor's Michigan License No.

504470 = BBC

PROFESSIONAL

July 18, 2013

For the Michigan Department of Natural R. Wuces, Polestines

20148 20149

DBM APPROVED BY BECHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975 Revised Jan., 1983 Rervised Oct., 1995