

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>36</u> N. S., R. <u>27</u> E. W.	<u>A-9, B-9, C-9</u>
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on September 17 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- A-9 S.W. section corner - Section 19; Wood post, W. Pine 20 - N32°W - 30 lks.; Aspen 14 - S29°W - 50 lks.
- B-9 South $\frac{1}{4}$ corner - Section 19; Wood post, Tam. 4 - N8°E - 42 lks.; Tam. 4 - S40°W - 13 lks.
- C-9 S.E. Section corner - Section 19; Wood post, Cedar 16 - N32°W - 15 lks.; Tam. 12 - S44°E - 14 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-9 Set on line between the West $\frac{1}{4}$ corner of Sec. 19 & the West $\frac{1}{4}$ corner of Sec. 30 & in centerline of road E & W. Corner falls between the N-S County road and the abandoned railroad grade of the Wisconsin Michigan Railroad Co., 44' west of the centerline of the N-S county road - 42' east of the centerline of railroad grade.
- B-9 Set on line between the S.E. and S.W. section corners of section 19 and prop. to G.L.O. record measurement. G.L.O. record measures to a ridge $\frac{1}{4}$ mile east fits very well.
- C-9 Set by double prop. to G.L.O. record using the section corners one mile north and one mile west and $\frac{1}{4}$ corners $\frac{1}{4}$ mile east and $\frac{1}{4}$ mile south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

ALL - 1" pipe, 4" aluminum cap.

- A-9 6" Twin Red Pine - N1°E - 54.5'; Power pole - N70°E - 87.6'; 9" Cedar - S61°E - 139.3'; 4" W. Birch - S61°W - 52.4'.
- B-9 4" B. Spruce - S22°W - 3.8'; 5" Tamarack - N37°W - 21.3'; 9" Tamarack - N46°E - 35.5'; 8" Tamarack - S86°E - 20.5'.
- C-9 8" Cedar - N84°W - 47.0'; 7" Cedar - S4°E - 26.6'; 12" Cedar - S82°E - 17.8'; 6" W. Birch N20°W - 18.5'.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY David B. Babbitt DATE 10-11-79
CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)SURVEYOR'S MICHIGAN REGISTRATION NO. 21558