

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>1</u> T. <u>36</u> N. S., R. <u>28</u> E. W.		K-3, L-3
2. PROPERTY CONTROLL- ING IN SECTION _____, T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

MENOMINEE
CO.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on May 18 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

K-3	L-3
S.W. Section corner	South $\frac{1}{4}$ corner
Wood post	Noted in the Wisconsin
Hem 20 - N65°E - 48	Michigan Railroad right-
W. Pine 18 - S23°W - 22	of-way plans but not
	described.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-3 Found 3/4" iron rod in centerline of roads N-E & W and in line with old fence south.
Not of record.

L-3 Sct 135' east of the centerline of old Wisc. Mich. Railroad grade and in line with the centerline of road west and an old fence east as shown on a sketch of the railroad right-of-way. Obtained from the Menominee Co. Road Comm. office. This position also fits an old N-S fence at the west 1/16 line of Section 1.
NOTE: This area had been excavated for a road ditch.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-3	L-3
1" pipe, 4" aluminum cap	1" pipe, 4" aluminum cap
6" red pine - S6°W - 54.0'	6" W. pine - S6°E - 105.5'
4" thorn apple - N26°E - 39.2'	R.L.S. Cap on power pole
Plastic R.L.S. cap in power pole	N22°W - 40.0'
N72°E - 77.4'	South end of 18" CMP road
	culvert - west - 14.4'

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____