

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee Located In: Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

9/11/2013AD
, Jeremy J. Pipp , in a field survey on 9/11/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(06) Northeast One-Sixteenth corner of Section 11. Not set in original survey, no
evidence of subsequent establishment.

(09) Center-East One-Sixteenth corner of Section 11. Not set in original survey, no
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(06) Corner position established at the intersection of the North and East One-
Sixteenth lines of Section 11. Position falls on existing E-W fenceline.

(09) Corner position established mid-point and on-line between the Center One-Quarter
corner and the East One-Quarter corner of Section 11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(06) DNR monument
8" Maple North 3.89' (1/16S,BT)
10" Maple S85E 28.74' (1/16S,BT)
11" Maple S51E 29.21' (1/16S,BT)
Gate Post N85W 11.92' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.
(09) DNR monument
3" Tamarack N43E 22.63' (1/16S,BT)
5" Cedar N74E 22.33' (1/16S,BT)
7" Cherry S37W 22.65' (1/16S,BT)
4" Maple N31W 25.30' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by [Signature] Date October 1, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources Forest Survey Division

