

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Menominee (County) Located In: Corner Code #
Public Land Survey
Property Controlling Section
Miscellaneous Property in Sec.

Lot No. Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 2/25/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
in this certificate.

c. Description of original monument and accessories and/or subsequent restoration:

(06) Northeast One-Sixteenth corner of Section 14. Not set in original survey. Found PS#44296
mapped rebar marking position.

(07) North One-Sixteenth corner common to Sections 13 and 14. Not set in original survey. 1968:
Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap witnessed by 8" Cedar N47W 05
links (3.30'), 7" Cedar S69E 10 links (6.60').

d. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(06) Accepted above described monument as marking Corner position; checks well for position at the
intersection of the North and East One-Sixteenth lines of Section 14. Set MDNR monument over
existing monument.

(07) Accepted found MDNR monument and Two witnesses (both living; NW BT leaning badly). Position is
accepted as a careful and faithful PERPETUATION of the position of the original corner.

e. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(06) DNR monument
5" Cedar N35E 6.92' (1/16S,NBT)
15" Cedar S44E 14.98' (1/16S,NBT)
5" Cedar S81W 3.08' (1/16S,NBT)
3" Cedar N44W 7.16' (1/16S,NBT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division

(07) DNR monument
6" Cedar N47E 34.86' (1/16S,NBT)
EX 7" Cedar S68E 7.00' (1/16S,BT)
7" Cedar S48W 4.78' (1/16S,NBT)
4" Cedar N41W 16.27' (1/16S,NBT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.



Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.