

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE  
(County)

Located in:

Corner Code #

1. Public Land Survey

T<sub>37N</sub> R<sub>25W</sub> E04

2. Property Controlling  
in Section

S<sub>---</sub> T<sub>---</sub> R<sub>---</sub>

3. Miscellaneous  
Property in Sec.

S<sub>---</sub> T<sub>---</sub> R<sub>---</sub>

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Aug. 20, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1852: Original Survey by George Adair - B.T.'s - Hemlock, 12" - N49°E - 25 lks.; Hemlock, 40" - S20°E - 24 lks. All original evidence for this corner has been destroyed by county road improvements.

1899: Survey by Albert Hass shows this corner as it relates to other corners in Section 8. Hass' record states "Set Cedar post from Government B.T."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We set this corner in line with the centerline of County Roads running East - West and South. This position fits well with GLO distances and with Hass' record distances to corners 1/2 mile North and 1/2 mile South, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum. cap stamped for corner location:

5" dia. Jack Pine	S28°E	57.34 feet	Scr. NBT
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S51°W	50.15 feet	1.1' NE of P. Pole
5" dia. Tamarack	N74°W	102.35 feet	Scr. NBT
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	North	33.75 feet	
Metal Survey Sign Post	North	34.30 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Dec. 20, 1996

