

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey

T37N. R. 25W

G07

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on Jul. 11, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by George Adair - B.T.'s - Hendock, 8" - N62°E - 23 lks.; Hemlock, 10" - S701/2°W - 90 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1985: L.C.R.C. No. 693 recorded by George B. Wilson, RLS No. 17607, states: "Set by using line of North - South Road and fence to the East." Set HDR Berntsen Monument 4-1/2 feet into ground." No B.T.'s are given. The back of this form shows this corner as it relates to other corners in Section 21, T37N-R25W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 3/4 inch diameter aluminum rod (5' long) with a 3-1/4 inch diameter aluminum cap (known as a HDR Berntsen Monument) on the West shoulder of a North - South County Road, and on line with an ancient fence line running East. This corner position fits well with corners 1/2 mile North (re-set from original B.T.'s), 1/2 mile South and 1/2 mile East (re-set from original B.T.), and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 3/4" dia. alum. rod/3-1/4" alum. cap stamped for corner location:

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S85°E	36.61 feet	1' NE of PP
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S40°W	27.73 feet	
5" dia. Spruce	N35°W	36.02 feet	Scr. NBT
Metal Survey Sign Post	S85°E	37.6 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Dec. 26, 1996

Date _____