And Alemontonee County
Cong Ramanumentation
Chemp Under Act 345 01

12/3/11, 199 6

Max Owen Res

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	r mng	requirement	VI 700 27, III										
MENOMINEE Locate	d In:	Corner Cod	e#	ŀ				 	33.55 15.05	Ŝ	: :		
(County)				ŀ	-				(D _{dh}	<u> </u>			
1. Public Land Survey	67N_R_2	5W		İ					() Z	نی	r in		
dono Edita Garraj	TR_							*		. 🔾	7.77		
•	ŢR_								. , Ø		T !		
2. Property Controlling S	T R		:						(2) (X	сò			
in Section S	TR_			l				., 1	'င္က ၂	(D)			
3. Miscellaneous S	ŢR									Ψ.			
Property in Sec. S	ı K					Reg	ster	of De	eds St	amp &	File N	umber	
4. Lot No, Recorded Plat 5. Private Claims				-	1 r	A B	<u> </u>	D E	FC	; <u>H</u>	I J	K L M	į
5. Private Claims					2	_ [5	4	 3	_ ₂ _	<u> </u>	I
					3	<u> </u>			\perp		 		ł
I, William Lenca , in a field survey on Nov. 06 , 19 96 do hereby state that under							•	8	 9	i0	ļi.	12	l
requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in											<u> </u>	_ _	l
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or								17	 _16	15	14-	13	
that the corner points mentioned in lines 3.4	and 5 above w	ere in conformanci	e with the rules of	' the Michigar	ո _	—18 ———————————————————————————————————		11		Ĭ.	 		l
Board of Land Surveyors or by a Decree recovered, found as expressed below:	of a Court of	Law; established,	re-established,	monumented	', g	 —19		20		22	23_	_ ! _ 24	
•					ا و		_	1					
NOTE: Not more than 2 corners, all in to on this certificate.	he same town	and range, may	pe recorded -		10			29_	28	27	26-		ı
Off this certificate.					11	\perp		.			_		1
					12	—31		32	_33	34_	35	36-	l
					 13					L.L			j
A. Description of original monument a	nd accessorie	s and/or subseq	uent restoration);									
1852: Original Survey by Geor original evidence for this	corner has be	en destroyed by	farming activ	ities.						**		,	
B. Description of corner evidence four	nd and/or met	hod applied in re	estoring or rees	tablishing c	orner:								
We set this corner at an ancient fer other corners in the area, and is ac	nce corner - 1 cepted as the	ences run East best available c	- West and No evidence of the	rth. The co	orner p f the or	ositi rigin	on fit al cor	s wel mer.		WII	ELIAM ENCA LAND ENCA ENCA ENCA ENCA ENCA ENCA ENCA ENCA		
C. Description of monument for corner Set 2" dia, Aluminum Pipe/3-1/4"	and accesso dia. Alum ca	ries established i p stamped for c	to perpetuate fo orner location:	ocating the p	position	of t	ne col	rner:	HAR	STERE	LAND	SURVERENCE	
5" dia. Ironwood	S650E	38.95 feet	Scr. NBT										
9" dia. Ironwood	S100W	21.48 feet	Scr. NBT										
12" dia. Maple 12" dia. Maple	S66 ⁰ W North	4.41 feet 11.76 feet	Scr. NBT Scr. NBT										
Survey Sign Post	N100E	11.76 feet	ou, NDI										
NOTE: All bearings are magnetic		•	meacured with	steel tane	Dista	nces	fo in	res at	e to na	ii in c	ide of t	rce	
-		is arounices ally	THE PERSON WILL	own tapo.				-ov ul	- 50 310		VI L		
Simulation (0) Plans .	Tener			Date	Dec. 2	26, 1	996						
	26461			Deta									
Surveyor's Michigan License No.			·									;	