

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/12 1996

Mike Davis PLS  
Chairman

For corners in

MENOMINEE  
(County)

Located In:

Corner Code #

1. Public Land Survey

T37N R 27W I-5  
T      R       
T      R       
T      R     

2. Property Controlling  
in Section

S      T      R       
S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R       
S      T      R     

4. Lot No.     , Recorded Plat     

5. Private Claims     

I, William Lenca, in a field survey on Oct 24, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1852: Original Survey by Francis Coleman - B.T.'s - W. Birch, 10" - N64°W - 26 lks; Cedar, 10" - S65°E - 34 lks. All original evidence for this corner has been destroyed by county road improvements.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We set this corner in line with county road centerlines running East - West and North and in line with a fence running South. This position fits reasonably well with measurements to existing corners 1 mile South and 1 mile West and with occupation lines to the East. We accepted this location as the best available evidence of the position of the original corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location 6" below gravel road surface:

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"  
12" dia. White Pine  
10" dia. Tamarack  
Metal Survey Sign Post  
Nothing else nearby

N40°E 57.43 feet 0.4' E. of Lrg. Fc. Post  
S24°E 105.59 feet Scr. NBT  
S30°W 84.78 feet Scr. NBT  
South 33.3 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Oct. 31, 1996