LAND CORNER RECORDATION CERTIFICATE

Menominee Located In: Corner Code ##	
1. Public Land Survey T 37N R 28W E-4-M.C., E-4, T R and E-5 M.C. T R R I R	
3. Miscellaneous S T R R Register of Deeds Stamp & File N 4. Lot No. Recorded Plat A B C D E F G H I 5. Private Claims A B C D E F G H I 6. David B. Babbitt, in a field survey on June 25th, 19 87, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: E-4 M.C. Meander corner common to Section 8 & 9. Wood post. Y. pine 6-S70E, .09	
4. Lot No, Recorded Plat	lumber
5. Private Claims David B. Babbitt in a field survey on	
1. David B. Babbitt, in a field survey on June 25th 19 87. 1. David B.	
I. David B. Babbitt, in a field survey on June_25th, 1987, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: E-4 M.C. Meander corner common to Section 8 & 9. Wood post. Y. pine 6-S70E, .09	<u> </u>
DO 6 - S83W, .06	-2 1 12 14 13 14
E-4. East ½ cor. of Section 8. Wood post. Cedar 18 - N23E, .23	
W. pine 18 - S7W, .31 E-5 M.C. Meander corner common to Sections 9 & 16. Wood post. Y. pine 14 - S53E, .41 DO 20 - N82E, .23	l
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
E-4 M.C. Set by meander line tie to rock outcrop recorded as S24E - 5.00 thence S9E -	8 00
from this corner. The rock outcrop is very definite and is the best available evidence of the original position of this meander corner. Measured northwest along the riverbank 13.00 chains from the rock outcrop. E-4. Set from the remains of a large cedar blow down and a white pine stump. Both very poor condition and I could not find any marks on them but bearings and distinct fit and the corner falls I chain south of a small stream C westerly as record the original notes.	e erly are in listances
E-5 M.C. Set mon. from SE OBT a y.pine stump with notch facing the corner. This corne calls, for a trail 0.25 chains east and meander calls for a rock outcrop S6½W thence S69W 2.00, very well.	r fits -2.50
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: E-4 M.C. DNR Monument. E-4. DNR Monument. E-5 M.C. DNR Monument 10" r.pine S26W, 7.2' 4" B.ash N69W, 16.4' 8" Cedar N45E, 30.1' 7" cedar N46W, 13.7' 6" B.ash N2E, 14.4' 6" R.pine S62E, 19.9' 7" w.birch N50E, 5.0' 8" H.maple N56E, 34.2' 10" Cedar S37E, 23.1' 3" r.pine S42E, 17.8' 15" w.pine S28E, 40.4' 12" W.pine S9E, 29.5'	

21558

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983