LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

-		
-or	corner	in :

Menominee	Located In:	Corner Code #								
(County)	-	-								
1. Public Land Survey	TR TR									
2. Property Controlling n Section	S 14 T 37N R 28W S 36 T 37N R 28W S T R	15 16								
3. Miscellaneous Property in Sec.	S T R S T R			Regis	ter of F	2 shee(tamp & I	≘ila Nu	mbo	
4. Lot No, Rec	corded Plat		ــــــ ۱۲	_	C D	E F	G H	I J		LM
	2/26/201	4	2	- 6	 - \$-		3-	- 	+	-¦
	n a field survey on 3/04/201	- an increase state	3 -	- -7_		9_	10-			
hat under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 bove were in conformance with regulations and rules therefore as required in the current manual of survey 5						\dashv				
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13 15 16 15 16 15 16 15 16 15 17 16 17 16 17 16 17 16 17 16 17 16 17 16 17 16 17 17 16 17 17 16 17 17 16 17 17 17 17 17 17 17 17 17 17 17 17 17					-1'3 					
he rules of the Michigan Board e-established, monumented, recov	d of Land Surveyors or by a Decree	of a Court of Law; established,	8 -	_19	20_	21-	22	2	-	-24-
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town and range,	may be recorded	10 11 12	-30- -31-	29	28-	27-	35	5—	-25 36
4. Description of original m	nonument and accessories and/or s	subsequent restoration:	134-							

- (15) West One-Sixteenth corner common to Sections 14 and 23. Not set in original survey, no evidence of subsequent establishment.
- (16) East One-Sixteenth corner common to Sections 36 [T37N-R28W] and 1 [T36N-R28W]. Not set in original survey, no evidence of subsequent establishment.
- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (15) Corner position established mid-point and on-line between the South One-Quarter corner and the Southwest corner of Section 14.
- (16) Corner position established mid-point and on-line between the South One-Quarter corner and the Southeast corner of Section 36.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) DNR	monument					
13" Spruce	N55E 8.26' (1/16S,BT)					
12" Tamarack	S52E 15.07' (1/16S,BT)					
4" Ash	\$80W 2.15' (1/16S,BT)					
5" Ash	NO3E 26.26' (1/16S,BT)					
All trees are blazed, scribed, and						
painted. Measurements are to nail in						
side of tree, bearings are magnetic.)						

(16)DNR monument 7" Cedar

N45E 31.11' (1/16S,BT) 8" Cedar S50E 19.65' (1/16S,BT) S33W 11.62' (1/16S,BT) Tamarack

N06W 11.38' (1/16S,BT) blazed, scribed, and Tamarack

mements are to nail in arings are magnetic.

PIPP

July 9, 2014

Surveyor's Michigan License No.

50447 For the Michigan Department of Natural Resour

20320

20321

AN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

Revised Jan., 1983 Rervised Oct., 1995