

SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. of 1990 On 12/30 199 2
Mike Davis RLS
Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION
For corners in
MENOMINEE

Located in: Corner Code #

1. Public Land Survey

T 38N R 27W M-02
T 38N R 26W (A-02)
T R
T R
T R
S T R
S T R
S T R
S T R

2. Property Controlling
In Section

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims
(SAME AS CORNER A-02 T38N-R26W) ✓

I, William Lenca, in a field survey on Nov. 07, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by H. Brevort - B.T.'s - Cedar, 4" - N63°W - 16 lks.; Fir, 6" - S53°W - 09 lks. All original evidence for this corner has been destroyed by logging activities.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We set a notched base county monument at an ancient fence corner shown to me by Gary Savord a long time resident who states this has always been accepted as the corner position. This position fits well with a GLO terrain call to a swamp edge 1 chain to the South and measures 2644.30 feet North of the SE Corner of Section 6 (M-3), and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

| | | | |
|---------------|-------|------------|----------|
| 8" dia. Cedar | N42°E | 23.75 feet | Scr. NBT |
| 7" dia. Cedar | South | 11.85 feet | Scr. NBT |
| 8" dia. Cedar | N79°W | 17.16 feet | Scr. NBT |
| 9" dia. Cedar | N19°W | 18.97 feet | Scr. NBT |



NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Nov. 18, 1997