

APR 06 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 12/30 1998
Mc Davis BLS
Chairman

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 38N R 28W G-07

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on Feb. 17, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1849: Original Survey by James H. Mullett - B.T.'s - Spruce, 8" - S33°W - 15 lks.; Sugar, 12" - S59°E - 30 lks. All original evidence for this corner has been destroyed by logging activities.
- 1903: Plat of Village of Harter by Thomas Hasley shows a tie to this corner. The corner monument is described as a Cedar Post.
- 1978: Certified Survey Number 21 by George B. Wilson shows a tie to this corner.
- 1986: Plat of Survey by Robert F. Perkins shows a tie to this corner and refers to it as an Iron Bar.
- 1995: Plat of Survey by William Lenca shows an existing Axle Shaft at this corner position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found an old axle shaft which falls in line with the centerline of a county road to the East, and with an old fence to the North. The Plat of the Village of Harter shows a distance from this corner East to the 1/16th Corner of 1299.5 feet. Our measured distance for this 1/4 mile is 1296.52 feet. The corner position also fits well with GLO terrain calls to a swamp edge 1.5 chains North, stream 4 chains East and 0.75 chains South. This corner has been accepted and used in several surveys, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

10" dia. White Spruce	S63°W	7.14 feet	Scr. NBT
8" dia. Cherry	N07°W	17.77 feet	Scr. NBT
South Rail of Railroad Track	North	135.85 feet	
Metal Survey Sign Post	South	1.3 feet	
Nothing else nearby			

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Dec. 23, 1998

Surveyor's Michigan License No. 26461

RECEIVED FOR RECORD
99 JAN -6 AM 8:56
PAGE # 730 BK 5
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49853

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		9		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

