

# SURVEY & REMONUMENTATION

JUN 23 1994

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 of

P.A. of 1990 On 5/18, 1994  
Mike Davis  
Chairman

For corners in  
MENOMINEE  
(County)

Located In:

Corner Code: F-9

- |                                       |   |             |
|---------------------------------------|---|-------------|
| 1. Public Land Survey                 | T <u>39N</u> R <u>26W</u>                 | <u>F-9</u>  |
|                                       | T <u>    </u> R <u>    </u>               | <u>    </u> |
|                                       | T <u>    </u> R <u>    </u>               | <u>    </u> |
|                                       | T <u>    </u> R <u>    </u>               | <u>    </u> |
| 2. Property Controlling<br>in Section | S <u>    </u> T <u>    </u> R <u>    </u> | <u>    </u> |
|                                       | S <u>    </u> T <u>    </u> R <u>    </u> | <u>    </u> |
| 3. Miscellaneous<br>Property in Sec.  | S <u>    </u> T <u>    </u> R <u>    </u> | <u>    </u> |
|                                       | S <u>    </u> T <u>    </u> R <u>    </u> | <u>    </u> |

RECEIVED FOR RECORD  
94 MAY 20 PM 3:32  
PAGE # 79 BK 4  
BARBARA MORRISON  
REGISTER OF DEEDS  
MENOMINEE, MI 49868

Register of Deeds Stamp & File Number

4. Lot No.     , Recorded Plat
5. Private Claims

I, William Lenca, in a field survey on May 18, 1994,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1852 - Original Survey by Harvey Mellen - B.T.'s - Cedar, 16", N55°E, 12 lks; Cedar, 14", N48°W, 17 lks. No evidence of  
the Original Bearing Trees was found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We set this corner on line and midway between the Northeast Corner and the Northwest Corner of Section 28 as indicated in the  
Original field notes. We then measured 127 feet West (1.92 chains GLO record) and 335 feet East (5.08 chains GLO record) to  
swamp edges. We found that the GLO record measurements fit well with the re-established corner position. We accepted this  
location as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Set 2-1/2" dia. Aluminum Pipe 30" long/3-1/4" dia. Alum. cap stamped for corner:

16" dia. Cedar	Scr. NBT	N88°E	10.39 feet
18" dia. Black Spruce	Scr. NBT	S16°W	16.07 feet
6" dia. Cedar	Scr. NBT	S84°W	12.37 feet
12" dia. Cedar	Scr. NBT	N18°W	34.39 feet
Carsonite Marker		S45°E	1.4 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date May 19, 1994  
Surveyor's Michigan License No. 26461