

SURVEY & REMONUMENTATION

JUN 23 1994

COMMISSION

For corners in
MENOMINEE

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 39N R 26W

G-9

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on May 9, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1852 - Original Survey by Harvey Mellen - B.T.'s - Hemlock, 14", S56°W, 17 lks; Cedar, 14", S68°E, 07 lks. Found remains of Cedar and Hemlock stumps in position matching original B.T.'s.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found remains of old squared wood post with point still in the ground. From this location we found the rotted remains of a Cedar stump and Hemlock stump which would match the position of the Original Bearing Trees. Due to the state of decay, we were unable to detect scribing. We then measured North 99 feet (1.5 chains GLO record) and West 165 feet (2.5 chains GLO record) to swamp edges. The GLO calls fit with the position of the old wood post. Based on the above information, we accepted the position of the old wood post as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 5/8" Aluminum Rod 3' long 3/4" dia. Alum. cap stamped for corner in place of old wood post:

18" dia. Hemlock	Scr. NBT	N87°E	33.23 feet
10" dia. Maple	Scr. NBT	S13°E	17.52 feet
8" dia. Maple	Scr. NBT	S79°W	25.79 feet
12" dia. Maple	Scr. NBT	N17°W	9.63 feet
Carsonite Marker		N25°E	2.0 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by

William Lenca

Date

May 19, 1994

Surveyor's Michigan License No.

26461

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 21
REVISED MAY 14
REVISED JAN

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 5/18 199 4

RECEIVED FOR RECORD
94 MAY 20 PM 3:32
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		

