

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

for corners in

Menominee Located In: Corner Code #
1. Public Land Survey T 40N R 26W 108
2. Property Controlling S T R
n Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

Jeremy J. Pipp, in a field survey on 7/02/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I08) Quarter corner common to Sections 22 and 23. 1852: Harvey Mellen, DS. Set Qr.
Section post witnessed by Tamarack 5 S73 1/2W 18 links (11.88'), Spruce 4 S89E 10 links
(6.60').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I08) Found probable OBT (Tamarack 5 S73 1/2W 18 links (11.88')), dead and down which
appeared to be facing the proper direction. Found definite Axe marks (Long upper/lower
face on proper East side; found upper blaze on West side), no scribing visible. No post
point recovered; several roots & wood debris found. Nothing found for corresponding OBT
SE; found 5" Balsam at this position. Location is only about 7 feet south of
proportionate position (and both Section corners 1/2 mile North and South were set from
OBT's, giving a strong search area); thus this position was accepted. Position is accepted
as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I08) DNR monument
6" Cedar N43E 20.61' (1/4S,NBT)
5" Spruce S61E 2.22' (1/4S,NBT)
10" Tamarack S06E 11.38' (1/4S,NBT)
7" Cedar N79W 16.01' (1/4S,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
metal sign post was set North 1.5 feet.

Signed by
Surveyor's Michigan License No. 50447



Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													