

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T 40N R 26W	I11
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

, Jeremy J. Pipp, in a field survey on 7/03/2013AD do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I11) Section corner common to Sections 26, 27, 34, and 35. 1852: Harvey Mellen, DS. Set  
Section corner post witnessed by Sugar 12 S81W 21 links (13.86'), Lynn 14 N32E 23 links  
(15.18'). 1971: Michigan DNR (Frank Bray PS#13575) Found 1/2 inch pipe, accepted then  
witnessed with 12" Aspen N37W 2.4', 18" Twin Balsam S65E 7.1', 8" Aspen S51W 11.8'. 2004:  
Michigan DNR (Paul Bressette PS#37270) Set 1" pipe with 4" Aluminum cap witnessed by 5"  
Ironwood N13E 27.8', 4" Sugar N78E 6.9', 5" Cherry S24W 29.5', EX 16" Aspen N40W 2.5'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I11) Accepted found MDNR Monument and remains of Four NBT's (two living, Aspen standing  
dead, Ironwood stump) as marking the Section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I11) DNR monument  
EX 7" Maple N76E 6.90' (S26,NBT)  
6" Balsam S31E 30.82' (S35,NBT)  
EX 6" Cherry S24W 29.47' (S34,NBT)  
3" Maple N15W 7.68' (S27,NBT)  
All trees are blazed, scribed, painted,  
and signed. Measurements are to nail in  
side of tree, bearings are magnetic. A  
metal sign post was set East 1.5 feet.

Signed by Jeremy J. Pipp  
Surveyor's Michigan License No. 50447



For the Michigan Department of Natural Resources, Forest Resources Division