MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_41 NR_26 T.

			Reposition
DESCRIPTION	OF	CORNER	Section Corner common to Sections 1,2,11,12
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Bress cap
WITTNESSES	то	CORNER	8* Ceder - N 64 E - 15 Links
			10* Ceder - 8 37 W - 44 Links
			12" Cedar - H 58 W - 44 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by Clarence Limpert, District Forester, of Escanaba. Two original B.T.'s still in place, in good condition.

Corner was placed and witnessed March 14, 1951.

SURVEYORS SEAL

SIGNED LEW C. Se la Meter DATE 4/2/51 _