

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling Section	S 1 T 41N R 26W	01
	S 1 T 41N R 26W	09
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

11/04/2013
Jeremy J. Pipp, in a field survey on 10/30/2013 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(01) West One-Sixteenth corner common to Sections 1 [T41N-R26W] and 36 [T42N-R26W]. Not set in original survey, no evidence of subsequent establishment.

(09) Center-East One-Sixteenth corner of Section 1. Not set in original survey, no evidence of subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(01) Corner position established mid-point and on-line between the North One-Quarter corner and the Northwest corner of Section 1. Monument set +/-6 feet South of the Centerline of a woods Road flush with the ground.

(09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 1.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(01) DNR monument
6" Tamarack N34E 28.82' (1/16S,BT)
11" Cedar S07E 39.15' (1/16S,BT)
10" Cedar S55W 49.46' (1/16S,BT)
7" Tamarack N28W 31.97' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by _____
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(09) DNR monument
7" Cedar N47E 5.98' (1/16S,BT)
5" Tamarack S53E 5.63' (1/16S,BT)
6" Spruce S66W 19.54' (1/16S,BT)
6" Cedar N60W 27.73' (1/16S,BT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Date August 25, 2014

