

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

| | | |
|-----------------------------------|------------------|---------------|
| Menominee (County) | Located In: | Corner Code # |
| Public Land Survey | T R | |
| | T R | |
| | T R | |
| Property Controlling n Section | S 16 T 41N R 26W | 06 |
| | S 16 T 41N R 26W | 07 |
| | S T R | |
| Miscellaneous Property in Sec. | S T R | |
| | S T R | |

1. Lot No. _____, Recorded Plat _____
2. Private Claims _____

Jeremy J. Pipp, in a field survey on 3/17/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
e-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(06) Northeast One-Sixteenth corner of Section 16. Not set in original survey, no evidence of
subsequent establishment.

(07) North One-Sixteenth corner common to Sections 15 and 16. Not set in original survey, no
evidence of subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(06) Corner position established at the intersection of the North and East One-Sixteenth lines of
Section 16.

(07) Corner position established mid-point and on-line between the East One-Quarter corner and the
Northeast corner of Section 16.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(06) DNR monument
7" Tamarack N56E 10.40' (1/16S,BT)
4" Tamarack S20E 22.35' (1/16S,BT)
10" Tamarack S46W 38.69' (1/16S,BT)
7" Tamarack N69W 10.22' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by _____
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(07) DNR monument
5" B. Spruce N27E 8.84' (1/16S,BT)
7" Cedar S76E 12.12' (1/16S,BT)
5" Tamarack S72W 7.08' (1/16S,BT)
6" Tamarack N33W 7.00' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Date July 9, 2014



| Register of Deeds Stamp & File Number | | | | | | | | | | | | |
|---------------------------------------|----|---|----|---|----|---|----|---|----|---|----|---|
| | A | B | C | D | E | F | G | H | I | J | K | L |
| 1 | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | |