

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 41N R 26W	C05
	T R	
	T R	
2. Property Controlling Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Jeremy J. Pipp, in a field survey on 8/07/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C05) Section corner common to Sections 7, 8, 17, and 18. 1852: E.C. Martin, DS. Set
section post witnessed by Cedar 18 S46E 14 links (9.24'), Hemlock 14 N30W 19 links
(12.54'). 2014: Found wood post by unknown persons.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C05) Accepted found old wood post with two types of ribbon and previously painted twice.
Found post is 5.37 feet south of a straight line position between Section corner one mile
West and Quarter Corner one & one-half miles East (also being 1.13 feet East of a single
proportionate position between said corners). Additionally, a possible stain in the soil
adjacent to found post. Also, a White Pine stump on a stilted mound S34E 12.4 Feet from
said location (would correspond to a possible OBT tip-out SE). Position is accepted as a
careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C05) DNR monument
5" Spruce N03E 29.32' (S8,NBT)
5" Spruce S80E 16.16' (S17,NBT)
6" Tamarack S43E 64.19' (S17,NBT)
7" Spruce S54W 55.30' (S18,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
Metal sign post was set North 1.5 feet.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447



Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													