

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Menominee (County) Located In: Corner Code #
Public Land Survey T 41N R 26W D03
T 41N R 26W E02
Property Controlling S T R
Section S T R
Miscellaneous S T R
Property in Sec. S T R

Lot No. Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 8/20/2014 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(D03) Quarter corner common to Sections 5 and 8. 1852: E.C. Martin, DS. Set quarter section post witnessed by Tamarack 12 S28W 19 links (12.54'), Tamarack 12 N08E 34 links (22.44'). 1981: Mead Corporation (Robert Schmeling PS#8317) Set 1" pipe with 4" Brass cap [from original evidence] witnessed by White Cedar 7 N18E 20.3', White Cedar 6 S20E 13.9', White Cedar 5 S50W 12.7', White Cedar 5 N41W 7.1'.

(E02) Quarter corner common to Sections 4 and 5. 1852: E.C. Martin, DS. Set quarter section post witnessed by W. Pine 18 S35E 34 links (22.44'), Hemlock 8 N34W 23 links (15.18'). 1955: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap [from original evidence] witnessed by 10" W. Pine N25E 50 links (33.00'), 12" Cedar S55E 48 links (31.68').

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D03) Accepted found Mead Corporation Monument, mound in place of OBT (SW), and Four NBT Witnesses (SE NBT noted as S20E; should have been S60E I assume. Cedar at correct distance S59E contains scribing and nail as called for in previous LCRC, no evidence at S20E.). New nails set directly above existing nails, only the nail heads remain visible for existing nails. Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

(E02) Accepted found MDNR Monument, stump remains OBT (SE), and Two NBT Witnesses (NE standing dead [cut down to obtain new NBT] and SE is a stump). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D03) Mead Corp. monument
EX 8" Cedar N20E 20.17' (1/4S5,NBT)
EX 7" Cedar S59E 14.00' (1/4S8,NBT)
EX 8" Cedar S51W 12.90' (1/4S8,NBT)
EX 6" Cedar N47W 6.96' (1/4S5,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set North 1.5 feet.
Signed by [Signature]
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division

(E02) DNR monument
9" W. Pine N25E 34.75' (1/4S,NBT)
8" Spruce N50E 27.33' (1/4S,NBT)
6" Tw. Maple S70W 48.08' (1/4S,NBT)
21" W. Pine N48W 78.54' (1/4S,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set North 1.5 feet.
Signed by [Signature] August 26, 2014



Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number. Contains numerical data for each cell.