

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County) Located In: Corner Code #
1. Public Land Survey T 41N R 26W G01
T 41N R 26W M03
2. Property Controlling in Section S T R
S T R
S T R
3. Miscellaneous Property in Sec. S T R
S T R
4. Lot No. Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 12 columns (A-M) containing numbers 1-36 for the Register of Deeds Stamp.

I, Jeremy J. Pipp, in a field survey on 8/12/2014 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G01) Section corner common to Sections 3 [T41N-R26W], 4 [T41N-R26W], 33 [T42N-R26W] and 34 [T42N-R26W]. 1846: John Burt, DS. Set section post witnessed by Cedar 6 N41E 13 links (8.58'), Spruce 7 N64W 31 links (20.46'). 1962: Kimberly Clark (Neal Sperhake PS#7876) Set 1" pipe with 4" Aluminum cap by proportionate method witnessed by Spruce 6 N18E 26 1/2 links (17.49'), Tamarack 5 N43W 31 1/2 links (20.79'), Tamarack 5 S17E 29 links (19.14') Tamarack 5 S48W 37 1/2 links (24.75').

(M03) Section corner common to Sections 1 [T41N-R26W], 12 [T41N-R26W], 6 [T41N-R25W], and 7 [T41N-R25W]. 1846: Austin Burt, DS. Set Cedar section post witnessed by Cedar 10 S64E 23 links (15.18'), Cedar 10 N52 1/2W 13 links (8.58'). 1955: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap [from original evidence] witnessed by 12" Y. Birch N22E 68 links (44.88'), 12" Sugar S49W 54 links (35.64').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G01) Accepted found Kimberly Clark Monument and Four NBT Witnesses (two living, two standing dead). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

(M03) Accepted found MDNR Monument, mounds in position of OBT's, and One NBT Witness (SW in good condition; NE destroyed by skid road construction). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G01) Kimberly Clark monument
7" Tamarack N36E 17.85' (S34,NBT)
EX 7" Tamarack S11E 18.79' (- , -)
7" Tamarack S29W 6.46' (S4,NBT)
EX 8" Tamarack N37W 20.96' (- , -)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set South 1.5 feet.
Signed by [Signature]
(M03) DNR monument
10" Maple N48E 33.21' (S6,NBT)
7" Cedar S34E 17.38' (S7,NBT)
EX 20" Maple S48W 36.06' (- , -)
10" Hemlock N54W 15.75' (S1,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set North 1.5 feet.

Surveyor's Michigan License No. 50447
For the Michigan Department of Natural Resources, Forest Resources Division
JEREMY J. PIPP
PROFESSIONAL SURVEYOR
No. 50447
Date August 25, 2014