

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

for corners in

Menominee (County) Located In: Corner Code #
1. Public Land Survey T 41N R 26W I03
T 41N R 26W K03
2. Property Controlling Section S T R
S T R
S T R
3. Miscellaneous Property in Sec. S T R
S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number
Table with 13 rows and 13 columns (A-M). Contains numerical data and a small graphic of a corner point.

8/12/2014
Jeremy J. Pipp, in a field survey on 8/12/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I03) Section corner common to Sections 2, 3, 10, and 11. 1852: E.C. Martin, DS. Set section post
witnessed by Cedar 12 S83W 20 links (13.20'), Cedar 12 N62E 11 links (7.26'). 1951: Michigan DNR
(Dean DeLameter PS#5778) Set 1" pipe with 4" Brass cap [from original evidence] witnessed by 12"
Cedar S28W 25 links (16.50'), 6" Cedar N46E 51 links (33.66'), 14" Cedar S14E 32 links (21.12').

(K03) Section corner common to Sections 1, 2, 11, and 12. 1852: E.C. Martin, DS. Set section post
witnessed by Tamarack 10 S40W 37 links (24.42'), Tamarack 10 N34E 41 links (27.06'). 1951:
Michigan DNR (Dean DeLameter PS#5778) Set 1" pipe with 4" Brass cap [from original evidence]
witnessed by 8" Cedar N64E 15 links (9.90'), 10" Cedar S37W 44 links (29.04'), 12" Cedar N58W 44
links (29.04').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I03) Accepted found MDNR Monument, stump mounds in position of OBT's, and One NBT Witness (SE in
good condition; SW is a stump; NE no trace). Position is accepted as a careful and faithful
PERPETUATION of the position of the original corner.

(K03) Accepted found MDNR Monument, trace remains of mound at OBT locations, and Three NBT
Witnesses (NW leaning, NE is a stump, & SW is standing dead). Position is accepted as a careful and
faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Table with 2 columns: (I03) DNR monument and (K03) DNR monument. Lists measurements for various trees and monuments.

All trees are blazed, scribed, painted, and signed. Measurements are to nail in
side of tree, bearings are magnetic. A Metal sign post was set North 1.5 feet.
All trees are blazed, scribed, painted, and signed. Measurements are to nail in
side of tree, bearings are magnetic. A Metal sign post was set South 1.5 feet.

Signed by [Signature] Date August 25, 2014
Surveyor's Michigan License No. 50447