

ALSO T42N-R26W K13
ALSO T42N-R26W L13
for corners in

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

Menominee	Located in:	Corner Code #
(County)		
1. Public Land Survey	T 41N R 26W	K01
	T 41N R 26W	L01
	T R	
2. Property Controlling Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

4. Lot No. , Recorded Plat
5. Private Claims

8/05/2014
Jeremy J. Pipp, in a field survey on 8/05/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K01) Section corner common to Sections 1 [T41N-R26W], 2 [T41N-R26W], 35 [T42N-R26W] and 36 [T42N-R26W]. 1846: John Burt, DS. Set section post witnessed by Spruce 5 N25E 6 links (3.96'), Spruce 5 N65W 28 links (18.48'). 1960: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap at found post with probable original bearing tree witnessed by 5" B. Spruce S69E 37 links (24.42'), 5" B. Spruce S53W 37 links (24.42').

(L01) Quarter corner common to Sections 1 [T41N-R26W] and 36 [T42N-R26W]. 1846: John Burt, DS. Set quarter section post witnessed by Spruce 4 N74E 34 links (22.44'), Spruce 4 N45W 26 links (17.16'). 1960: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap by proportionate method witnessed by 4" B. Spruce N23E 10 links (6.60'), 4" B. Spruce S68W 38 links (25.08').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K01) Accepted found MDNR Monument and One NBT Witness (SE dead and down). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

(L01) Accepted found MDNR Monument and One NBT Witness (NE standing dead). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K01) DNR monument
4" B. Spruce N56E 8.72' (S36,NBT)
4" B. Spruce S43E 11.01' (S1,NBT)
4" B. Spruce S67W 10.89' (S2,NBT)
3" B. Spruce N08W 9.65' (S35,NBT)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set South 1.5 feet.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(L01) DNR monument
3" B. Spruce S08E 14.38' (1/4S,NBT)
3" B. Spruce S39W 13.70' (1/4S,NBT)
4" B. Spruce N86W 16.13' (1/4S,NBT)
5" B. Spruce N35W 19.78' (1/4S,NBT)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set South 1.5 feet.

Signed by
Date August 25, 2014

JEREMY J. PIPP
PROFESSIONAL SURVEYOR
No. 50447

20413

20412



Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7			8			9			10		11	12
5													
6	18			17			16			15		14	13
7													
8	19			20			21			22		23	24
9													
10	30			29			28			27		26	25
11													
12	31			32			33			34		35	36
13													

Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995