LAND CORNER RECORDATION CERTIFICATE LSO T41N-R25W A01 Filing Requirement of Act 74, Mich. P.A. 1970 as Amended or corners in Menominee Located In: Corner Code # (County) I. Public Land Survey 41N R 26W T M01 T T R Property Controlling n Section S Т R S 3. Miscellaneous S R Property in Sec. Register of Deeds Stamp & File Number 1. Lot No. , Recorded Plat 5. Private Claims Jeremy J. Pipp , in a field survey on 8/18/2014 do hereby state hat under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 bove were in conformance with regulations and rules therefore as required in the current manual of survey $^{\sf S}$ nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 . Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 he rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 e-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(MO1) Township corner common to Sections 1 [T41N-R26W], 6 [T41N-R25W], 31 [T42N-R25W], and 36 [T42N-R26W]. 1846: John Burt, DS. Set township post witnessed by Y. Birch 22 N59E 8 links (5.28'), Lynn 22 S59W 40 links (26.40'). 1960: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap [at found wood post with possable original evidence] witnessed by 9" Hard Maple S51W 53 1/2 links (35.31'), 10" Hard Maple S47W 44 1/2 links (29.37'), 10" Ironwood N34W 43 1/2 links (28.71'), 10" Hard Maple N75W 34 1/2 links (22.77'), also noted in this record Existing 24" Hard Maple N75W 34 1/2 links (22.77').

10

11

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MO1) Accepted found MDNR Monument, One NBT Witness (NW "existing" Maple in good condition; no traces of other record NBT's), and several other existing witness trees facing corner. Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR monument EX 19" Maple N53E 29.78' (- , -) 9" Maple 26.01' S44E (S6, NBT) EX 18" Basswood S82W 26.26' (\$36,NBT) 11" Maple N31W 12.48' All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set South 1.5 feet Signed by

Surveyor's Michigan License No.

PROFESSION SURVEYOR

0122

August 25, 2014

For the Michigan Department of Natural Resources, Forest Re

(MO1)