

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Missaukee Located In Corner Code #
 (County)

1. Public Land Survey T 21N R 5W M6
 T R
 2. Property Controlling S T R
 in Section S T R
 3. Miscellaneous S T R
 Property in Section S T R

4. Lot No: - Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Sept. 07, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M6 – 1837 – GLO – J. Brink – Set ¼ Section Post

1) Cedar 10" S16°W 22 L.

2) Beech 8" N30½°W 29 L.

- 1907 – CSR – FB #40, p. 66 – J. D. McBain - Cedar stake set by Skeels – 1906

- 1911 – H. M. Belknap – Fd. Corner est. by Skeels. Made no new bearings.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M6 – ¼ Corner common to Section 13, T21N, R5 W, & Section 18, T21N, R4W – Searched 40' radius area for Cedar stake called for by McBain and Belknap. No evidence of corner or GLO BT's. Set 4" DNR Alum. Cap on a 1" X 48" iron pipe midway and on line between corners 'M5' and 'M7'. Measure North 67°± (264' – GLO) to S. Edge of old river channel – course – SE. Measured Grid distance of 2615.67' vs. 2640' – GLO to 'M5' & 'M7'. DNR Mon. accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M6 – 4" DNR Alum. Cap on 1" X 48" long galvanized iron pipe.
 Set Blue Carsonite Post 1' North

N15°E 13.56' to set N & T in E side 14" W. Oak scribed 'XBT'
 S86°E 18.28' to set N & T in N side 7" W. Pine scribed 'XBT'
 S75°E 35.95' to set N & T in S side 13" Cedar scribed 'XBT'
 N88°W 16.16' to set N & T in S side 8" W. Oak scribed 'XBT'
 N51°W 46.12' to set N & T in NE side 13" & 7" twin Cedar scribed 'XBT'



Signed by: Craig W. McVean
 Surveyor's Michigan License No.: 39088

Date: 11/18/2010