

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Missaukee  
(County)

Located In

Corner Code #

1. Public Land Survey

T

R

2. Property Controlling  
in Section

S 26

T

21N

R

6W

6

3. Miscellaneous  
Property in Section

S

T

R

S

T

R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on February 27, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

2013-01546 L: L-7 P: 2313 LCORNER  
04/30/2013 12:18:10 PM Page 1 of 1  
Carolyn Flores County Recorder, Missaukee County MI

Register of Deeds Stamp &amp; File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - NE 1/16 corner section 26

1992 - LCRC L. 281, P. 385 - C. Roser, PS #12028 -  
Established SE cor of NW ¼ of NE ¼ of sec 26 per  
standard BLM instructions. Center of Trail NNW is 73'  
west. Drove 5/8" x 34" rerod w/RLS cap. Set cedar post  
with location tag. -  
1) 11" R Pine N15°W 28.0', 2) 4" W Pine N35°E 29.4',  
3) 4" Maple(CLP5) S50°E 11.4', 4) 2" W Pine S60°W 6.9'

9 - CE 1/16 corner section 26

1992 - LCRC L. 281, P. 385 - C. Roser, PS #12028 -  
Established NW cor of NE ¼ of SE ¼ of sec 26 per  
standard BLM instructions. Center of 5' to 12' wide creek  
is 10' ± 3' to west. Creek flows S-SE'ly. Drove 1" x 96"  
galv. pipe with RLS Cap. Set cedar post with location tag.  
1) 2" Elm N80°W 34.2', 2) 3" Tw Maple N63°W 88.1',  
3) 11" W Pine N20°E 105.2', 4) 8" W Pine N60°E 74.1'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

6 - NE 1/16 corner section 26

Found 5/8" rebar & cap #12028 per Roser LCRC. Also found  
Roser's accessories fitting position. Accepted found rebar  
and cap as the best available evidence of the position of the  
corner.

9 - CE 1/16 corner Section 26

Found 1" galvanized iron pipe with cap #12028 per Roser  
LCRC. Also found Roser's accessories 2, 3 & 4 fitting  
position. Accepted found 1" galvanized iron pipe with RLS  
cap #12028 as best available evidence of the position of the  
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - 5/8" rebar &amp; cap #12028. Cedar post with location tag 0.8' NW.

N28°E 29.69' to set nail & tag in NW. side 8" White Pine (2)  
S64°W 7.09' to set nail & tag in SE. side 12" White Pine (4)  
N12°W 28.48' to set nail & tag in W. side 17" Red Pine (1)  
S47°E 11.39' to set nail & tag in NE. side 9" R. Maple  
in Clump of 4 (3)

9 - 1" galvanized iron pipe with cap #12028. Cedar post with  
location tag 1' Northwest.

N20°E 105.68' to set nail & tag in W side 20" W. Pine (3)  
N62°E 74.66' to set nail & tag in NW. side 18" W. Pine (4)  
N63°W 88.18' to set nail & tag in NE side twin 8" R. Maple (2)  
N15°W 3.14' to set nail & tag in E. side 7" Elm

Signed by:

*Joshua R. Davidson*

Date:

4-30-2013

Surveyor's Michigan License No.:

46659

