

JAN 13 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 333 PAGE 417

#1329

For corners in

Missaukee Located In: Corner Code #
(County)

1. Public Land Survey	T 21N	R 07W	I-12
	T	R	
	T	R	
	T	R	
2. Property Controlling in Section	S	T	R
	S	T	R
3. Miscellaneous Property in Sec.	S	T	R
	S	T	R

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 09 1999 3:55 PM

Carolyn Flare
Register of Deeds Stamp & File
Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William E. Sikkema, in a field survey on August 15, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-12, One-quarter Corner common to Section 34 and Section 35, T21N, R7W; Post set in original government survey by Deputy Surveyor, Colman in August of 1856. Corner witnessed by:
N44°W - 10" Hemlock - 17 Links S20°E - 30" W. Pine - 8 Links
County Surveyor E. Beuthien notes from October 1912 calls for a gas pipe. Corner witnessed by:
S51°E - 30" W. Pine Stump - 39 Links S48°W - 20" W. Pine - 67 Links
McClung LCRC #564 of 1977 - Fd 1" pipe in intersection with no evidence of original witness. Witnessed by:
S55°E - Tele Box - 44.80' West - Fence Post - 31.25'
James H. Grainger Certificate of Survey in 1993 fd 1" pipe as recorded in LCRC #564.
Craig Pullen certificate of survey in 1999 - fd 1 1/2" pipe in CL Vandermullen Rd, 4.5' S of CL Brinks Rd. Witnessed by:
N44°E - Top CTR Tel Ped - 56.98'; N46°E - 1/2" iron - 46.60'; S56°E - Fence Post - 51.85'; S48°E - TopCenter T.Ped-44.88'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-12, Found 1" iron pipe of record. 4 feet South of Centerline Brinks Rd., 2 feet West of Centerline Van Dermullen. This corner fits McClung witnesses of 1977. This corner is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12
Replaced 1" Pipe with 1/2" by 18" rebar with Brass Miss. County Mon. stamped #45505, 1999.
Tele Box - N48°E - 57.35'
Fd nail W side corner Fence Post - S52°E - 45.26'
Set nail NE side 6" Twin Aspen - N45°W - 25.44'
Fd nail N. Side of Fence Post-West-31.25'
Telephone Riser-S55°E-44.80'



Signed by William E. Sikkema

Date 11/03/99

Surveyor's Michigan License No. 45505

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Peer Group Reviewed and Approved

Date: 10-9-99

J. Dean Geers, Missaukee Co. Representative

REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995