

MAY 28 1997

COMMISSION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 308 PAGE 715

#1084

For corners in
Missaukee
(County) Located In: Corner Code #

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 20 1996 2:45 P.M.

Carolyn Flare
REGISTER

Register of Deeds Stamp & File Number

1. Public Land Survey T 21N R 7W M-6
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, J. Dean Geers, in a field survey on December, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- M-6) 1837 GLO Quarter Section Post by John Brink, Deputy Surveyor; Hemlock 11-S68W-15; Beech 8-N45W-38
M-6) 1892 County Survey in Section 18, T21N, R6W; Corner was used but no wit's recorded.
M-6) 1971 Cavanagh LCRC, Liber 1, pg 8; 1/2" x18" Steel Bar, Wit: 1/2" Bar-S88E-33.02
M-6) 1986 Wilcox LCRC, Found Iron of record, N85W-Corner Fence Post-44.57; N43W-Corner Fence Post-56.63; S83E-Corner Fence Post-35.06; N69E-12" R. Pine- 71.97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M-6) Corner Common to Section 13, T21N, R7W and Section 18, T21N, R6W; Reset corner as recorded by using existing witnesses. Corner is in centerline of North-South Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- M-6) Set 1/2" Iron and Missaukee Co. Mon. in mon. box
N45W - 50.85 - Set wit. Iron
N87W - 33.68 - Fence Post
S85E - 35.08 - Corner fence post
N60E-62.72 - 12" Red Pine

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by *J. Dean Geers*
Surveyor's Michigan License No. 733977

Date 12-19-96