BUTIVEY &

REMONUMENTATION LIBER <u>308 PAGE</u> 708 MAY 28 1997 LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 #1077 For corners in Missaukee Located In: Corner Code # MISSAUKEE COUNTY MICHIGAN 22N_R 6W 1. Public Land Survey RECORDED DEC 2 0 1996 AM. Т **Property Controlling** __T __ in Section Τ. 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section , Recorded Plat_ 4. Lot No. 5. Private Claims J. Dean Geers , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: M-10) 1837 GLO Quarter Section Post by John Brink, Deputy Surveyor; Cedar 10-S57W-6; Beech 8-N57W-15 B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Quarter Corner Common to Section 25, T22N, R6W and Section 30, T22N, R5W; Reestablished corner midway and on line between the section corners one half mile to the North and South. Corner falls in North-South fence line and 13' North of fence line to the West. This corner is accepted as a careful and faithful reestablishment of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-10) Set Miss. Co. Mon. on 1/2" Iron

Signed by Surveyor's Michigan License No SURVEYOR 3677

S18E - 66.13 - 8" Elm

N 40W- 27.93 - 3" Ash N40E - 32.22 - Set wit. iron

S (484) 30

South - 14.63 - Corner Fence Post

Date 12-19-96

Form approved by Michigan State Board of Professional Surveyors, Jan. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

Peer Group Reviewed and Approved

J. Dean Geers, Missaukee Co. Representative