

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee

(County)

Located In

Corner Code #

1. Public Land Survey T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling in Section S 31 T 22N R 8W 4  
S 31 T 22N R 8W 5  
3. Miscellaneous Property in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Craig W. McVean, in a field survey on July 14, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

4 - None

5 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4 - NW 1/16, Section 31, T22N, R8W.  
Set 2" Stamped aluminum cap on 5/8" x 34" rebar per standard BLM procedure. West 24.5'± to centerline NW-SE 2-track

5 - CN 1/16, Section 31, T22N, R8W  
Set 2" Stamped aluminum cap on 5/8" x 34" rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4 - 2" Stamped aluminum cap on 5/8" x 34" rebar  
N4°W 23.62' to set N & T in W. side 8" triple R. Maple  
N76°E 8.34' to set N & T in N. side 4" Oak  
S50°E 2.54' to set N & T in NE side 4" Oak  
S13°W 20.37' to set N & T in W. side 2" R. Pine  
Set Blue Carsonite Post with location tag 1' NE

5 - 2" stamped aluminum cap on 5/8" x 34" rebar  
N6°E 36.89' to set N & T in E. side 9" R. Maple  
N70°E 21.59' to set N & T in N. side 8" Beech clp. 4  
S3°W 37.93' to set N & T in W. side tri 10" R. Maple  
N68°W 22.13' to set N & T in N. side twin 8" Beech  
Set Blue Carsonite Post with location tag 1' NW

Signed by:

Craig W. McVean

Date:

5/11/2006

Surveyor's Michigan License No.:

39088