

SURVEY &
REMONUMENTATION

MAY 28 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

1102

For corners in

Missaukee County
(County)

Located In:

Corner Code #

1. Public Land Survey T 22N R 7W B-13
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

LIBER 308 PAGE 895

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 30 1996 4:30 P.M.

Caslyn Klare
REGISTER
Register of Deeds Stamp & File
Number

I, Daniel E. Schripsema, in a field survey on October 1, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		5			4			3		2			1
3													
4		7		8		9		10		11			12
5													
6		18		17		16		15		14			13
7													
8		19		20		21		22		23			24
9													
10		30		29		28		27		26			25
11													
12		31		32		33		34		35			36
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-13) 1837 GLO survey by John Brink, Deputy Surveyor - set quarter section post - Beech 10" N27E 59
1898 survey, page 63 of county surveyor field notes - Cement Block, S 37
1890 survey, page 77 of county surveyor field notes - Cement Block fence stump S 47
1917 survey, county surveyor field notes - Cement Block wit. - F.P. S 32'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-13) Quarter Section corner common to section 31, T22N, R7W, and section 6, T21N, R7W. Found 1" square bar next to concrete block in north and south fence, and centerline 2-track east. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1" square bar with 1/2" iron and Miss. Co. remonumentation cap.
S10E 17.25' 6" Cherry (Fd Nail)
N06E 33.96' 10" Twin Cherry (Fd Nail)
N69W 44.70' 28" Maple (Fd Nail)
S46W 66.87' 10" Jack Pine
South 1.83' Fence Post (Fd Nail)

Peer Group Reviewed and Approved

Date: 12-30-96
J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by: *Daniel E. Schripsema*
DANIEL E. SCHRIPSEMA
SURVEYOR

Surveyor's Michigan License No. 24617

Date 12-30-96