

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Missaukee

(County)

Located In

Corner Code #

1. Public Land Survey T 23N R 5W L6
T
2. Property Controlling in Section S 13 T 23N R 5W 8
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Sept. 9, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

L6 - None

8 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L6 - C 1/4 Sec. 13, T23N, R5W - Found 1/2" x 18" capped rebar #33977 WAI (Geers). Fits intersection of 1/4 lines closely. Talked to Dean Geers but he could not find any history on this monument due to lack of index to Wilcox files he has. Centerline of Gravel road is 36' South. Remains of N-S fence is 13'± East. 1/2" CIR accepted as the best available evidence of the position of the corner.

8 - CW 1/16 corner Sec. 13 - Set stamped 2" Aluminum Cap on 5/8" x 34" rebar per Standard BLM procedure. Centerline of E-W gravel road is 110'± North. Centerline of oil well road is 50'± East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L6 - Replaced 1/2" x 18" CIR #33977 with stamped 2" Aluminum Cap on 5/8" x 34" rebar. Set Blue Composite Post with loc. tag 1' West. N26°W 27.33' to set N & T at fd. nail in W. side 8" Birch N59°E 20.10' to set N & T at Fd. nail in S. side 16" R. Pine N79°E 3.54' to set N & T at fd. nail in S. side 11" R. Pine S66°W 15.39' to set N & T in NW side 8" R. Pine N64°W 12.20' to set N & T in NE side 11" R. Pine

8 - Stamped 2" Aluminum Cap on 5/8" x 34" iron rebar. Set Blue Composite Post with loc. tag 1' SE N88°W 40.55' to set N & T in N. side 5" Cherry N27°E 166.59' to set N & T in SE side 13" R. Maple N89°E 112.62' to set N & T in N. side 5" Cherry S28°E 119.60' to centerline Oil Well head

Signed by:

Craig W. McVean

Date:

2/23/2015

Surveyor's Michigan License No.:

39088