

JAN 30 1996

1026

COMMISSION

LAND CORNER RECORDATION CERTIFICATE MISSAUKKEE COUNTY MICHIGAN
Filing Requirement of Act 74, Mich. P.A. 1970For corners in
Missaukee

(County)

Located In:

Corner Code #

RECORDED JAN 2 1996 1:15 PM

Angela Flare
REGISTER

1. Public Land Survey	T	23	R	6	E-13
	T		R		
	T		R		
	T		R		
2. Property Controlling	S		T	R	
in Section	S		T	R	
3. Miscellaneous	S		T	R	
Property in Sec.	S		T	R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Daniel E. Schripsema, a field surveyor on August, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- E-13) 1837 GLO post by John Brink, Deputy Surveyor
 Hemlock 10 N35°W 6, Beech 10 N57°E 26
 E-13) 1917 Beuthien Notes: Fieldbook #9, pages 50-51
 E-13) 1917 Beuthien Notes: Fieldbook #9, pages 90-91
 E-13) 1975 Wilcox LCRC, Liber-page 191: Found empty Mon. Box
 E-13) 1975 Wilcox survey, Liber S-1, page 241: Found empty
 Mon. Box in centerline intersection
 E-13) 1976 Wilcox survey, Liber S-1, page 253: Found empty Mon. Box
 (continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- E-13) Section Corner common to Sections 32 and 33

Found empty monument box in centerline M-55, centerline gravel Rd. North
 1.6' West centerline Rd. South. This corner is accepted as a careful and faithful
 perpetuation of the location of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- E-13) Placed Mon. Box and Brass Missaukee County Monument on existing corner with #24617.

S76°W	166.99	P.Pole
N36°W	63.48	Cor. Fnce. Post
S52°E	61.72	Cut-off P.Pole
* N33°E	59.00	4"x4" conc. ROW Mon.
N68°E	136.16	P.Pole

* = Old witness

Peer Group Reviewed and Approved

Date: 1-2-96
J. Dean Geers
 J. Dean Geers, Missaukee Co. Representative

Signed by Daniel E. Schripsema
 Surveyor's Michigan License No. 24617

Date 12-29-95