

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MISSAUKEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 23N R 7W

F-5

T R

T R

T R

T R

2. Property Controlling  
In Section

S 9

T R

12

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, CARL T. KIISKILA, in a field survey on JANUARY 13, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-5

12

U.S. G.L.O. SET QUARTER SECTION POST; BEECH 6 N82°W 15 LINKS,  
BEECH 5 S35 1/2°W 16 LINKS.

E.A. BEUTHIEN 1909 " GAS PIPE; WPS 30 N20 1/2°W 92, WPS 30  
N29 1/2°E 119.

M. MYERS, P.S. 831600 1988 CERT OF SURVEY "FOUND PK NAIL REPLACED  
W 1/2" x 18" BAR; SW COR RR TIE POST S45°E 31.08', SP IN N. FACE  
4" POPLAR WEST 49.95, NAIL IN E FACE MAILBOX POST N15°E 80.33',  
1/2" BAR & CAP EAST 33.00".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-5

12

FOUND AND ACCEPTED 1/2" REBAR PER M. MYERS 1988 CERT. OF SURVEY  
DATA.

ESTABLISHED NE COR OF W1/2 OF SW1/4 PER STANDARD BLM PROCEDURE.  
CORNER FALLS IN CTR OF N-S BIT. ROAD. N-S WOOD FENCE IS 35' WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-5

12

FOUND 1/2" REBAR W/CAP PER MARV. MYERS, PLACED 1" x 1' IRON PIPE  
W/CAP OVER. CTR OF N-S BIT. RD. IS 2.5' WEST.  
S87°E 33.09 TO CAP 1/2" REBAR.  
N87°53'W 33.02 TO CAPPED 5/8" x 3/4" REBAR & CARB. POST.  
N70°W 43.67' TO N & T IN N. SIDE 4" W. PINE "XBT".  
N36°W 78.45' TO N & T IN NE SIDE 21" BEECH "XBT".  
S56°W 118.8' TO N & T IN SE SIDE 10" R. PINE "XBT".  
S54°E 31.10' TO SET N & T IN SW COR RR TIE.  
8 MM WIT.

SET 5/8" x 3/4" REROD W/PS CAP.  
N55°E 61.13' TO N & T IN NW SIDE 7" W. PINE.  
N56°W 38.15' TO N & T IN NE SIDE 16" R. PINE.  
S61°W 48.40' TO N & T IN N SIDE 9" R. PINE.  
N87°34'W 33.03' TO CAP 5/8" x 3/4" REBAR (35' TO CARSONITE POST).

Signed by

Carl T. Kiiskila

Date

5-16-97

Surveyor's Michigan License No.

33981

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

