## **Land Corner Recordation Certificate**

Authority: 1970 PA 74, MCL 54.205

	Surveyor's Name: Craig W. McVean						Field Survey Date: Aug. 31, 2017								
r corner(s) in: Missaukee				County											
Original Public Land Survey Corner															
Т		R													
Т		R			_	4 B (	c n i	= F (	3 H 6	1 1	< 1 I	M,			
Т		R			- 1j					3 1		1			
Т		R			2	6	5	4	3	2	1	2			
				0	3				i		H	3			
ng Corner				Corner Code	4	7	8	9	10	-11	12	4			
<u> </u>	_				- 5	i	_ i_	-i-	-i-	- i -	1	5			
		-			- 6	- 18 -	17	-16	- 15	11.	-12	6			
Т.									Į,	1.4	13	1			
Т_		_R _			_ `]				•	-	-	7			
				Corner Code	- 1	19	20	21	22	23	24	8			
т	23N	P	7\//		~						erenne fan en	9			
		-0-			_10	30	29	28	27	26	25	10			
	23N			5	-11						i	11			
					- 12	31	32	33	-34	35	36	12			
т		_R_			- 1			00	0,1	00	30				
Land Surve	v Corr	ner		Corner Code	- /	A B (	CDE	FC	H	J	( L i	վ 13 И			
Т	,														
· _					-										
					-										
<u>_</u> -					_										
	nd Survey T T T T T T T T T T T T T T T T T T T	nd Survey Corner T T T T T T T T T T T T T T T T T T T	T	T R T R T R T R T R T R T R T R T R T R	Corner Code	Corner Code	T	T	T	T R T R T R T R T R T R T R T R T R T R	T R T R T R T R T R T R T R T R T R T R	Corner Code			

## Part A: Corner History

N 1/16 Corner common to Sec. 21 & 22, T23N, R7W
 Record Survey – L. 264, p. 1253 – R. L. Wetherell (PS #24624). Shows intersection of N 1/16 line and E. Sec. line Sec. 21.

<u>5</u> – CN 1/16 Corner Sec. 22, T23N, R7W - None

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- 3 N 1/16 Corner common to Sec. 21 & 22, T23N, R7W Set 2" Alum. Cap on 5/8" x 34" long iron rebar per Standard BLM procedure. Down remains of N-S woven wire fence is 8'± East. Centerline of E-W 2-track is 23'± North.
  - Reference Pt. N89°57'W 24.67' from '3' found ½" rebar with steel fence post guard. This iron fits mid-point between 'G8' and rejected position near 'G7'. ½" iron rebar not utilized as '3' in this survey.
- 5 CN 1/16 Corner Sec. 22, T23N, R7W Set 2" Alum. Cap on 5/8" x 34" long iron rebar per Standard BLM procedure. Single strand wire S. is 6' West Single strand wire E. is 14.5'± North

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

- 3 N 1/16 Corner common to Sec. 21 & 22, T23N, R7W Stamped 2" Aluminum Cap on 5/8" x 34" long iron rebar. Set Blue Composite Post with Loc. Tag 1' SE. S25°E 5.62' to set N & T in W. side 3" W. Pine N58°W 28.80' to set N & T in NE side 3" W. Pine S67°W 13.02' to set N & T in N. side 3" W. Pine N89°57'W 24.67' to Fd. ½" rebar Reference Pt.
- 5 CN 1/16 Corner Sec. 22, T23N, R7W Set Blue Composite Post with Loc. tag 1' SW S19°E 17.90' to set N & T in W. side 16" R. Pine S42°W 18.60' to set N & T in SE side 16" W. Pine N17°W 7.66' to set N & T in E. side 17" W. Pine S86°E 13.03' to set N & T in N. side 20" W. Pine



Craig W. McVean

Date

Professional Surveyor's License No.: 39088

Prepared By: Craig W. McVean

Michigan Dept. of Natural Resources

8015 Mackinaw Trail Cadillac, Michigan 49601