

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Missaukee
(County)
Located In
Corner Code #
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Section
4. Lot No:
5. Private Claims:

Register of Deeds Stamp & File Number

I, Craig W. McVean, in a field survey on July 11, 2007 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Table with 13 rows and 13 columns (A-M). A dot is marked at the intersection of row 3 and column D.

A. Description of original monument and accessories and/or subsequent restoration:

- D3 - 1853 - GLO - T. Whelpley - Set 1/4 Section Post
1) Beech 8" N19°E 7 L.
2) Beech 5" S24°W 17 L.
- 1914 - CSR - FB# 35, p. 57; OB OK,
3) WPS 48 South 46
- 1975 - LCRC #188 and Record Survey L. S-1, p. 219 -
J. L. Wilcox. Set 1/2" iron. Set from old witness.
4) N15°E 15.15' - 14" Maple
5) N40°W 23.80' - 8" Maple
6) S60°E 33.45' - 4" Maple

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D3 - 1/4 Corner common to Sections 5 & 8, T23N, R7W - Searched area and did not find Wilcox iron, probably removed by recent logging. Found old post hole with rotten wood and fence remains East and West. Position fits witness #3 and stumps of Wilcox witnesses #4, #5 and #6. Set stamped 2" Aluminum cap on 5/8" x 4' long rebar in post cavity with ring of cobblestones. The 2" Aluminum cap on 5/8" x 4' long rebar accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D3 - Stamped 2" Aluminum cap on 5/8" x 4' long rebar with ring of cobble stones.
Set Blue Carsonite Post 1' North.

Old Bearing Trees
N05°E 15.44' to set nail in top of centerline of 17" Maple stump (#4)
N60°W 24.10' to set nail in top of centerline 8" Maple stump in clump (#5)
S55°E 33.71' to set nail in top of centerline 14" Maple stump (#6)
South 31.45' to set 1/2" x 18" rebar in centerline of remains 48" White Pine Stump (#3)

New Bearing Trees
N69°E 22.89' to set nail and tag in North side 11" White Pine scribed 'XBT'
S58°E 48.86' to set nail and tag in Southwest side 16" Beech scribed 'XBT'
S19°W 26.97' to set nail and tag in East side 7" Oak scribed 'XBT'
N63°W 39.29' to set nail and tag in North side 9" White Pine scribed 'XBT'



Signed by: [Signature] Date: 11/24/2008
Surveyor's Michigan License No.: 39088