

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


_____**MISSAUXEE**_____
COUNTY
T _____**26 N**_____ R _____**6 W**_____

DESCRIPTION OF CORNER _____**S 1/4 corner, Section 7**_____

CORNER MONUMENT _____**Found 1 1/2" pipe - added DNR Monument**_____

DATE MONUMENT PLACED AND WITNESSED _____**8-10-71**_____

WITNESSES TO CORNER..... _____**4" Rock Elm**_____ **S 51 E** _____ **51.0'**



_____**4" Rock Elm**_____ **S 23 W** _____ **27.1'**

_____**5" Rock Elm**_____ **S 78 W** _____ **37.6'**

AND
In Ctr. E-W Fire Lane (Twp Rd)
_____**Pa. Co.**_____ **Due W** _____ **2.5'**

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1 1/2" pipe, fits occupancy and corner by proportion very closely.



SURVEYOR'S SEAL

SIGNED _____**Carl F. Rover**_____ DATE _____**8-17-71**_____

REGISTERED LAND SURVEYOR
12028

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68