


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

MISSAUXEE COUNTY  
T 24 N R 6 W

DESCRIPTION OF CORNER SE corner of Section 12  
CORNER MONUMENT Replaced Fd. 1/2" pipe with DNR Mon. buried in Rd. intersection.  
DATE MONUMENT PLACED AND WITNESSED 7-28-71  
WITNESSES TO CORNER.....




16" Red Pine	N 69 W	135.82'
12" Trpl Maple	N 27 W	142.05
18" Oak	N 43 E	64.40'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1/2" pipe in road intersection as recovered and witnessed by Geo. E. Young,  
R.L.S. #10710, Oct. 1966.



SURVEYOR'S SEAL

SIGNED Carl F. Roser DATE 8-2-71  
REGISTERED LAND SURVEYOR 12028

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68