

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 24 N. R. 7 W


Missaukee COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 11-12-13-14

CORNER MONUMENT Left 1 1/4" pipe in place below surface

DATE MONUMENT PLACED AND WITNESSED May 3, 1966

WITNESSES TO CORNER.....



1 1/4" H. Maple	S 82 E	51.5'
18" H. Maple	N 66 W	41.5'
2 1/4" Hemlock	N 21 E	49.1'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township. Found 1 1/4" pipe in concrete cylinder below surface, at south edge of trail road E-W. Probably established by County Surveyor in early survey of this township. Old fence line North. Appears acceptable to pattern of survey of this area.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Bethong* DATE May 6, 1966  
REGISTERED LAND SURVEYOR #10068