

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 24 N. R. 7 W.	C-12; C-13; D-13; E-13
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	, RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 30, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

C. (continued)

E-13
 Fd. 1/2"x18" Rerod w/RLS Cap in ctr. of E-W gravel road
 9" Maple S38°W 43.65
 7" Maple N38°E 43.76
 7" Maple N31°W 42.62
 N-S R.R. Grade Due W 65'±
 Set cedar post w/loc. tag N 33'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- C-12** Fd. old conc. mon. per J. G. Cavanagh 1909 survey. Although this E 1/4 corner of Sec. 31 seems to be considerably short S to SE Sec. 31 (2487.95'); an 1895 Sec. 31 (sec. sub.) survey, notes in back of brown field books-GLO & Beuthien-at Co. Rd. Comm., indicate a mean prorated distance of the E side of SE 1/4 of Sec. 31 to be 2489'±.
- C-13** Fd. rerod as set by RLS J. Erickson (Erickson-Wilcox & Assoc.). Corner falls in approximate center E-W gravel road.
- D-13** Fd. & accepted iron as set by RLS Erickson. Approximate center E-W gravel rd. is 3'± S.
- E-13** Found and accepted iron as established by RLS J. Wilcox.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-12	C-13	D-13
Fd. 1" pipe in conc. & set cedar post w/loc. tag	Fd. 1/2" rerod w/RLS Cap #16929	Fd. 1/2" Rod w/RLS Cap #16929
12" Maple N85°E 8.6	11" Maple N45°W 51.29	21" Twin Oak N35°W 42.85
12" Maple N49°W 37.0	16" Maple N15°W 39.18	7" Maple S10°W 37.08
8" Maple S27°E 10.8	12" Maple S17°E 37.97	6" Maple N50°E 43.59
	Set cedar post w/loc. tag Due N 33'	Set cedar post w/loc. tag Due N 33'

SIGNED BY Carl F. Roser 5-13-81 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

MISSAUKEE COUNTY
PIONEER TOWNSHIP

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

