LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Missaukee Located In: Corner Code #	
1. Public Land Survey T_24N R_7WD-10	
TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L M 2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12
I, <u>Craig W. McVean</u> , in a field survey on <u>April 1</u> , 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 28 27 26 25 11 12 31 32 33 34 35 36 36 36 36 36 37 38 38 38 38 38 38 38 38 38 38
A. Description of original monument and accessories and/or subsequent restoration: D-10 - Not Set in GLO Survey - Rec. Survey S-1, P. 460 - 471 - Set 5/8" x 18" Iron w/Cap in Swamp - H. Fluharty - 1978 5" Spruce S50" W 41.36' 5" Spruce S14" E 14.12' 6" Spruce N88°E 21.16' 7" Cedar N32°W 8.81'	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO. 39088
B. Description of corner evidence found and/or method applied in restoring or reestablishing D-10 - Center of Section 29 - Set 4" Department of Natural Resources A.C. on 1" x 96" Galve of 1/4 lines per BLM Procedure - N-S Fence is 16' + W - Monument accepted as the beposition of the corner. Reference Pt "D" - FND Capped Iron per Rec. Survey S-1, P. 460-471. Monument was position based on a single prop. position for the W 1/4 of Sec. 29. J. G. Cavanagh mo W 1/4 that was Sly of SP Position. Iron Rod Monument was established using improper utilized as D-10 in this survey.	corner: I Iron Pipe in swamp at intersection est available evidence of the s established using a latitudinal nument was later found @
C. Description of monument for corner and accessories established to perpetuate locating	the position of the corner
D-10 - 4" A.C. as per Part 'B' - Set Carsonite guard post. N55° E 43.02' to N&T in 8" Cedar S68° E 44.28' to N&T in 4" Cedar \$20° W 33.23' to N&T in 6" Cedar \$44° W 34.10' to N&T in 5" Cedar Reference Pt. "D" - 4.16' N & 0.16' W - Capped 5/8" x 18" Rebar	are position of the corner:
Signed by Cruig W. Mullan Surveyor's Michigan License No. 39088	Date <u>9/10 /1997</u>
and the second of the second o	

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN., 1983
REVISED OCT., 1985