SURVEY & REMONUMENTATION

JAN 1 6 1998			
SECTION	LAND CORNE Filing Requir	R RECORDATION CERTIF ament of Act 74, Mich. P.A.	1970
For corners in			LIBER 314 PAGE 125H
Missaukee (County)	Located in: Con	ner Code#	MISSAUKEE COUNTY MICHIGAN
1. Public Land Survey	T 24NR 7W	H-13	RECORDED NOV 1 0 1997 430
1. Public Land Survey	TR TR		Caulyn Flore
a a sect Controlling	s T R		Carolin Flore
2. Property Controlling in Section	S TR		REGISTER
3. Miscellaneous	\$ IR \$ T R		Register of Deeds Stamp & File Number
Property in Sec.	<u></u>		
Popol	rded Diat		A B C D E F G H I J K L M
4. Lot No, Reco	rded Plat		1 2 6 5 4 3 2 1
J. Fillato Clamb		•	3
	lunc	97 do haraby state that til	
J. Dean Geers	in a field survey on	19 97 do hereby state that unmentioned in lines 1 and 2 above we urrent manual of survey instructions o	re in 5
formance with fellilities of	Id tales allowers at the		U/U 6 10 1 1 1 1 1 1
Linked Chalce Department of the	ilifelior ' Dalego of Taire		
Daged of Land Surveyors or a	by a Decise of a commercial	stablished, re-established, monume	8 19 20 21 22 23 24
recovered, found as expressed t	solution.	nge may be recorded	3 27 26 25
NOTE: Not more than 2 co on this certificate.	omers, all in the same town and ra	(1gs, 11.5) 5 5 5 5 5	10 30 29 28 27 28
On this Certificate.			11 32 33 34 35 36
			12—31——32——
· .			13
A. Description of original n	nonument and accessories and	or subsequent restoration.	27 - 16 77 - 10 N 53 F - 16
	a stangartion Post by John Bi	ink, Deputy Surveyor; Beech 8-	N78W-45, Hemlock 10-N53E-16 plar 6-S36E-54
H-13) 1838 GLO (H-13) 1909 Cavan	agh County Surveyor; Set Rails	ink, Deputy Surveyor, Become oad Iron; Poplar 6-S60E-86, Po ound Iron; S53E-49,75-20" Tam	arack, S23E-40.15-NW corner garage,
S16E- H-13) 1981 DNR	LCRC, Liber 1, Page 624; Four	ad Narrow Gauge Railroad Iron,	Raised with 5/8"x36" Rerod; S54E-comer garage, S69W-70.95-
49.74	-21" Tamarack, 544E-55.1"10	nd Narrow Gauge Ranroad fron, E corner garage, S13E-62.9-SW	Comp. B
Telep	phone Pole ox Survey, Liber S-3, Page 343	Found Iron as recorded	
H-13) 1995 Wilco	ox but vey, blook o o, - ve	applied in restoring or reestablish	ing corner:
B. Description of corner	evidence ioniid andioi memora	- F	15/0" Iron as
	ion Corner common to Section	34, T24N, R7W and Section 3,	T23N, R7W, Found 5/8" Iron as his comer is accepted as a careful and
H-13) Quarter Sect recorded in 1	Liber 1, Page 624. Corner is in	centerline of road East-West. 1	his corner is accepted as a careful and
faithful perp	etuation of the position of the or	aginal cortiel.	
		•	
		,	
•		,	
	termore and accessofies	established to perpetuate locating	g the position of the corner:
 C. Description of monur 	Heur to: commer and accessomed		
Table Dat Micani	kee County Monument on exist	ing Iron	
NR6F 10	8.69 20"1 amarack		Peer Group Reviewed and Approved
S75E 12	6.67 6" Tamarack		Date:
S51E 49 S70W 70			
S24W 10		Pana.	J. Dean Gers, Missaukee Co. Representative
	A Comment	A Comment of the Comm	
	JOY J. DEAL	N. A. S.	
	GEERS) } D	ete
Signed by	3397X No.	OR C	
Surveyor's Michigan Lic	cense NoNoNo	737	

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995